

Message Text

UNCLASSIFIED

PAGE 01 NICOSI 01324 140931Z

16

ACTION SY-05

INFO OCT-01 EUR-12 ISO-00 /018 W
----- 128098

P R 140900Z APR 75
FM AMEMBASSY NICOSIA
TO SECSTATE WASHDC PRIORITY 1507
AMCONSUL FRANKFURT PRIORITY
INFO AMEMBASSY ATHENS

UNCLAS NICOSIA 1324

DEPT FOR A/SY/T; FRANKFURT FOR RTC; ATHENS FOR TSO

E. O. 11652: N/A

TAGS: ASEC

SUBJECT: CCTV - REQUEST FOR TECHNICAL ASSISTANCE

1. DURING INSTALLATION OF CCTV SYSTEMS IN NICOSIA
AN MTC-21 MK II CAMERA MALFUNCTIONED WHICH THE TSO
HAS BEEN UNABLE TO REPAIR.

2. WHEN POWER IS APPLIED TO CAMERA VIDEO OUTPUT AS VIEWED
ON MONITOR IS EXCELLENT. AFTER WARMUP OF FIVE TO TEN
MINUTES, PICTURE BEGINS TO BREAK UP WITH HORIZONTAL
OSCILLATIONS. RATE OF BREAK UP IS ABOUT ONE EVERY SECOND
BECOMING SOMEWHAT FASTER AS UNIT HEATS UP. UNIT CAN BE
SWITCHED TO FREE RUN TO ELIMINATE HORIZONTAL BREAK UP;
HOWEVER, THIS PRODUCES SOME WAVING OF THE PICTURE AND
DARK HORIZONTAL BARS DRIFTING VERTICALLY ON THE
MONITOR SCREEN.

3. TSO HAS ADJUSTED R114 IN AN ATTEMPT TO CORRECT THE
PROBLEM IN THE 50HZ POSITION AND TO REDUCE THE INTER-
FERENCE IN THE FREE RUN POSITION. ADJUSTMENT OF R114
DID NOT CORRECT EITHER PROBLEM. TSO SUSPECTS THERMAL
RUN AWAY OF TS101 OR TS103 IN MIANS LOCK CIRCUIT.

A. CAN SY/T SUGGEST FURTHER FIELD MODIFICATION OR
ADJUSTMENT TO CORRECT HORIZONTAL BREAK UP?

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 NICOSI 01324 140931Z

B. CAN SY/T OR RTC FRANKFURT PROVIDE A REPLACEMENT
MTC-21 MK II CAMERA? TSO DOES NOT HAVE A SPARE UNIT.

4. TSO PLANS TO BE IN NICOSIA UNTIL ABOUT APRIL 30.
FYI - OF THE NEW CCTV EQUIPMENT TO BE INSTALLED, TSO
HAS FOUND THREE CAMERAS, ONE MONITOR, AND ONE 50-FOOT
CABLE WHICH REQUIRED REPAIR.
CRAWFORD

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 14 APR 1975
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Authority: n/a
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1975NICOSI01324
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D750129-0404
From: NICOSIA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1975/newtext/t19750453/aaaabwxml.tel
Line Count: 69
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION SY
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Review Action: RELEASED, APPROVED
Review Authority: ShawDG
Review Comment: n/a
Review Content Flags:
Review Date: 30 JUN 2003
Review Event:
Review Exemptions: n/a
Review History: RELEASED <30 JUN 2003 by maginmm>; APPROVED <22 JAN 2004 by ShawDG>
Review Markings:

Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
05 JUL 2006

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: CCTV - REQUEST FOR TECHNICAL ASSISTANCE
TAGS: ASEC
To: STATE FRANKFURT
Type: TE
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 05 JUL 2006